





BOSS PROPORTIONER TEMPERATURE CONTROLLER WIRING DIAGRAM



- 1 - Empty
- 2 - Purple thermocoupler (TSU)
- 3 - Red Thermocoupler (TSU)
- 4 - Red Solid State Relay (Novus/Crydom)*
- 5 - Black Solid State Relay (Novus/Crydom)
- 6 - Empty
- 7 - Empty
- 8 - Black Power wire from switch
- 9 - Red Power wire from switch

* Can also be a white wire